



Replaced clip-on plug and crimp-on wire connectors on the front passenger-side fender mounted turn indicator.

Connectors are all flush within the plug, and withstood a tug test.
Plug snapped into place with little effort indicating proper alignment.
No indication of crimp-on connectors shifting backward.



Turn indicator works after replacement.
Wire harness was tugged and wiggled with no adverse affect to turn indicator operation.