

UHL TRK OF KENTUCKIANA

4300 POPLAR LEVEL ROAD - LOUISVILLE, KY 40213

Phone: (502) 451-8360 - Fax: (502) 473-4600 (Service Writer: Bill Cundiff - Date: 4/20/2021 9:34 AM C)

Estimate #3169892 Prepared For

Boy Scout Troop 243

PO BOX, Louisville, KY 40250 (primary)

Phone: (1) 502-2985340 - Fax: () - (VIN: 4DRBRAAN64A968033 - Unit: TROOP243)

Repair Management

UHL TRK OF KENTUCKIANA

4300 POPLAR LEVEL ROAD - LOUISVILLE, KY 40213

Phone: (502) 451-8360 - Fax: (502) 473-4600 Estimate Number: 3169892 - RO Number: N/A Service Writer: Bill Cundiff - Date: 4/20/2021 9:34 AM (C)

Currency: USD



Unit No: TROOP243

Boy Scout Troop 243

VIN: 4DRBRAAN64A968033 Model: CE SCHOOL BUS

Engine: INTL DT466 HT 215HP/2400 GOV

Make: International Delivered: 5/4/2004

In Service: 16 Years 11 Months

Mileage: 0 Eng Hrs: 0

Recall/AFC: No

Contact Name: FRANK FRANK

Position: service-primary Phone: (502) 298-5340

E-Mail: B.CUNDIFF@UHLTRUCKSALES.COM

PO Number:

Operation (All Sections)	Labor Cost	Parts Cost	Core Charge	Total Cost
B Service	\$252.00	\$272.00	\$0.00	\$524.00
DIAGNOSE LOW AIR BUZZER	\$280.00	\$0.00	\$0.00	\$280.00
REPAIR LOW AIR BUZZER	\$140.00	\$0.00	\$0.00	\$140.00
Exhaust Pipe, Replace	\$1,190.00	\$3,190.86	\$0.00	\$4,380.86
(2) CLAMP, EXHAUST PIPE 4" (1) CLAMP, EXHAUST PIPE, CLAMP, TURBOCHARGER PIPE TO TURBOCHARGER 4 INCH (1) CLAMP, EXHAUST, 3.5 IN. HD, PREFORMED, LAP JOINT, ALUM (1) CLAMP, EXHAUST, 4.0 IN. HD, PREFORMED, LAP JOINT, STAINLESS (1) PIPE, TAIL HUMP SECTION (1) PIPE, TAIL 276" WHEEL BASE (1) PIPE, EXHAUST INLINE 6 NGD ENGINES (1) PIPE, TAIL MUFFLER TO TAIL PIPE 276" WHEEL BASE (8) CLAMP, MUFFLER 4" (1) MUFFLER,ASM EXHAUST (1) SUPPORT, MUFFLER (1) SUPPORT ASSY MUFFLER				

Notes:

[4/20/2021 9:34 AM] - Dealer: ESTIMATE FOR PM SERVICE, DOT, LOW AIR BUZZER WORKS INTERMITENTLEY AND REPAIR EXHAUST

SYSTEM

Parts:	\$3,462.86
Core:	\$0.00
Labor:	\$1,862.00
Shop:	\$150.00
Tax:	\$328.49
Haz. Waste:	\$15.00
TOTAL:	\$5,818.35

Currency: USD

Page: 1 of 1

This estimate is subject to teardown and inspection and is valid for 30 days from date above. I, the undersigned, authorize you to perform the repairs and furnish the necessary materials. I understand any costs verbally quoted are an estimate only and not binding. Your employees may operate vehicle for inspecting, testing and delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it.

Authorized	Signature	X

Customer: Boy Scout Troop 243 **Mileage:** 0 **RO:** N/A

Vehicle: CE SCHOOL BUS VIN: 4DRBRAAN64A968033 Date: 4/20/2021

B Service

Qty	Part Number	Part Name	Price (ea)	Total
		No parts assigned		

DIAGNOSE LOW AIR BUZZER

Qty	Part Number	Part Name	Price (ea)	Total
		No parts assigned		

REPAIR LOW AIR BUZZER

Qty	Part Number	Part Name	Price (ea)	Total
		No parts assigned		

Exhaust Pipe, Replace

Qty	Part Number	Part Name	Price (ea)	Total
2	FLTXC40AF	CLAMP, EXHAUST PIPE 4"	\$6.48	\$12.96
1	FLTEC425VBS	CLAMP, EXHAUST PIPE, CLAMP, TURBOCHARGER PIPE TO TURBOCHARGER 4 INCH	\$23.61	\$23.61
1	FLTEC35PLA	CLAMP, EXHAUST, 3.5 IN. HD, PREFORMED, LAP JOINT, ALUM	\$7.78	\$7.78
1	FLTXC40PLS	CLAMP, EXHAUST, 4.0 IN. HD, PREFORMED, LAP JOINT, STAINLESS	\$11.88	\$11.88
1	3544141C1	PIPE, TAIL HUMP SECTION	\$673.19	\$673.19
1	3543496C1	PIPE, TAIL 276" WHEEL BASE	\$858.62	\$858.62
1	2004557C1	PIPE, EXHAUST INLINE 6 NGD ENGINES	\$295.95	\$295.95
1	3543906C1	PIPE, TAIL MUFFLER TO TAIL PIPE 276" WHEEL BASE	\$645.35	\$645.35
8	282400C1	CLAMP, MUFFLER 4"	\$24.56	\$196.48
1	2018471C1	MUFFLER,ASM EXHAUST	\$238.37	\$238.37
1	2013206C91	SUPPORT, MUFFLER	\$115.23	\$115.23
1	1660540C91	SUPPORT ASSY MUFFLER	\$111.44	\$111.44